

To Whom It May Concern:

April 10, 2017

As of February 2nd 2017, The Quemado Lake Volunteer Fire Department was awarded an ISO 7 rating. A copy of that rating from the Insurance Services Office is attached.

Currently there are 52 fire hydrants throughout the Quemado Lake Estates subdivision which is serviced by the Quemado Lake Volunteer Fire Department. No structure within the subdivision is more than 500 feet from a fire hydrant.

In 2015 the QLVFD added a 2000 gallon engine-tender to its fleet of fire fighting vehicles. An engine donated by the San Diego County, California Fire District was acquired in 2016.

Sincerely,

A handwritten signature in cursive script that reads "Michael D. McDoniel".

Mike McDoniel, QLVFD Chief

Summary of PPC Review

for

Quemado Lake FPSA

| FSRS Item | Earned Credit | Credit Available |
|---|----------------------|-------------------------|
| Emergency Communications | | |
| 414. Credit for Emergency Reporting | 1.20 | 3 |
| 422. Credit for Telecommunicators | 3.33 | 4 |
| 432. Credit for Dispatch Circuits | 1.95 | 3 |
| 440. Credit for Emergency Communications | 6.48 | 10 |
| Fire Department | | |
| 513. Credit for Engine Companies | 4.08 | 6 |
| 523. Credit for Reserve Pumpers | 0.00 | 0.5 |
| 532. Credit for Pumper Capacity | 3.00 | 3 |
| 549. Credit for Ladder Service | 1.85 | 4 |
| 553. Credit for Reserve Ladder and Service Trucks | 0.00 | 0.5 |
| 561. Credit for Deployment Analysis | 3.57 | 10 |
| 571. Credit for Company Personnel | 1.94 | 15 |
| 581. Credit for Training | 0.38 | 9 |
| 730. Credit for Operational Considerations | 1.00 | 2 |
| 590. Credit for Fire Department | 15.82 | 50 |
| Water Supply | | |
| 616. Credit for Supply System | 15.90 | 30 |
| 621. Credit for Hydrants | 1.18 | 3 |
| 631. Credit for Inspection and Flow Testing | 0.00 | 7 |
| 640. Credit for Water Supply | 17.08 | 40 |
| Divergence | -2.21 | - |
| 1050. Community Risk Reduction | 1.18 | 5.50 |
| Total Credit | 38.35 | 105.5 |

Final Community Classification = 07/7X